Eisenhower Interstate Highway Stormwater Conveyance System

Grafton, ND (Installed about 1950)

Galvanized Corrugated Steel Pipe

Owner

North Dakota DOT

Contractor

Unknown

Consulting Engineer

North Dakota DOT

Application

Stormwater Conveyance

Why this product versus others?

Corrugated steel pipe was used to replace failing concrete pipe

Special project elements

This installation was performed more than 60 years ago. Recent inspections show the pipe to be in excellent condition.





