

10th St. Storm Drain Replacement

| Fargo, ND

Polymer Coated Spiral Rib CSP Storm Drain

Owner

City of Fargo, North Dakota

Contractor

Northern Improvement Company

Consulting Engineer

North Dakota DOT

Application

Storm drain replacement

Why this product versus others?

Lower installed cost versus RCP

Project challenges

Compact and congested construction site

Special project elements

Removal of corrugated steel pipe installed in the late 1930s and replaced it with new polymer coated corrugated steel pipe with a projected 100+ year design life



TrueNorth Steel®

TrueNorthSteel.com | info@TrueNorthSteel.com