Ransom County Crossing FEMA Repair | Enderlin, ND

CSP Aluminized Steel Type II and Corrugated Headwalls, 12 Ga. 60" Dia.

Owner

Ransom County Highway Department

Contractor

Ransom County Highway Department

Consulting Engineer

Ransom County Highway Department

Application

FEMA repair

Why corrugated steel pipe from TrueNorth Steel?

FEMA requirement to replace damaged pipe with similar materials

Project challenges

Removal of existing pipe and backfill

Special project elements

New corrugated headwall ensured proper flow into pipe and protected against overtopping.





