

Slate Creek Aquatic Organism Passage

| Hill City, SD

128"x83" Arched Culvert Replacement Project

Owner

Black Hills National Forest & Rocky Mountain Region

Consulting Engineer

Black Hills National Forest & Rocky Mountain Region

Application

Watershed rehabilitation and aquatic organism passage

Why this product from TrueNorth Steel?

Cost effective and ease of installation

Project Challenges

High stream flows in June 2015 washed out two undersized culverts on Slate Creek Dam Road. A road closure was put in place for safety reasons, but vehicles were fording the creek causing resource damage.

Special/unique elements of the project

The washed-out culverts were contributing sediment into the stream and impeding aquatic organism passage. The newly installed culvert allowed free movement of aquatic organisms and reduced sediment input into the creek.



TrueNorth Steel®

TrueNorthSteel.com | info@TrueNorthSteel.com