

# Elk Creek Crossing Bridge Replacement | Richland County, ND

## Structural Plate Bridge Solution

### Owner

Richland County, North Dakota

### Contractor

Richland County Highway Department

### Consulting Engineer

Interstate Engineering

### Application

Bridge Replacement

### Why this product versus others?


- Clear span opening
- Low maintenance

### Project challenges

Marginal bearing capacity due to silty sand conditions

### Special project elements

Corrugated steel structure was positioned above the normal flow of the creek on concrete footings



**TrueNorth Steel**®

TrueNorthSteel.com | info@TrueNorthSteel.com