

BNSF Rehabilitation | DEVILS LAKE, ND

120" Dia 8 Ga. 5x1 Galvanized Pipe

Owner
BNSF

Contractor
BNSF

Consulting Engineer
Houston Engineering

Application

A 120" diameter galvanized pipe was used to reline an existing concrete structure. Contractor stated "... an impressive product was delivered and banded together with very little effort".

Special/unique elements of the project

The original plan for a more structural backfill did not work and since they basically just needed to fill the void, a local ready mix supplied a non-shrink solution mixture that met those requirements.

