



DRAINAGE CULVERTS

ANTELOPE CREEK BRIDGE REPLACEMENT



LOCATION	SIZE	COMPLETION DATE	SCOPE
Grant County, ND	8ga 2x 144" CSP	2023	CSP Beveled End Treatments

During the harsh 2022-23 winter season, the wooden bridge abutments over Antelope Creek were damaged by ice beyond repair. While water flow is minimal throughout the year, a significant rain event could easily cause the bridge to fail, removing all access to and from various farms on the other side of the creek. Because of this, and the quickly approaching winter, the timeline for this project was very short. Additionally, the county had limited funds for this project as they are given a set budget each year to make repairs/replacements. Grant County weighed its options and ultimately chose TrueNorth Steel's steel solution over competitors' concrete options due to lead time and cost. In the end, TrueNorth Steel successfully completed this project on time and within budget.